

Nothe Fort Weymouth- Risk Assessment

Hazard	Risk	Likelihood	Control Measures
Steps, kerbs, and general changes of height	Trips and falls	Medium	<p>Edges of kerbs and steps to be highlighted with white paint Changes in slope to be painted with chevrons</p> <p>Teachers to inform students that due to the nature of the building there are uneven surfaces and care needs to be exercised.</p>
Vertical drops greater than 2.0 from the Ramparts	High risk of serious injury from falls	Risk eliminated by provision of safety fence	<p>Safety fencing and warning signs to be maintained in a good state of repair. No member of the public to be allowed to climb or cross the safety fence.</p> <p>Teachers to highlight danger to students prior to entering the fort</p>
Slippery Surfaces	Minor injury	High	<p>Slippery surfaced to be regularly brushed to remove algae</p> <p>Signs to be erected where appropriate</p>
Electrical equipment	Electrical shock	low	<p>All portable electrical equipment to be PAT tested.</p> <p>Electrical distribution cupboards to be locked. All electrical installations to be regularly inspected</p> <p>Teachers to instruct students on the dangers of interfering with electric equipment</p>

Nothe Fort Weymouth - Risk Assessment

Hazard	Risk	Likelihood	Control Measures
Very steep grassed banks adjacent to the ramp leading to the Ramparts. Steep ramp leading to the Ramparts. Steep banks at Rampart level	Slipping or falling down the bank or slope resulting in minor injury	Medium	Teachers to advise students regarding playing and running on steep slopes
Low light levels	Tripping on steps and causing minor injury	Medium	Edges of kerbs and kerbs to be highlighted with white paint, changes in slope to be painted with chevrons Teachers to instruct students to take care in areas where there are low light levels
Drops of approximately 1.5 m from gun platforms	Serious Injuries arising from falls	Low	Existing safety fencing and netting to be maintained in a good state of repair Teachers to instruct students to keep off the safety netting.
Falls and knocks whilst climbing on the Scout Car and Anti aircraft gun.	Cuts and bruising	Medium	Teachers to instruct students to take care whilst playing on scout car and anti aircraft gun. Students to keep off all other exhibits
Low temperatures at Basement Level	Hypothermia	Low	Teachers to highlight the need to bring warm clothing